

[View this email in your browser](#)



Friday, 19 November 2021

We have stopped crushing at Inkerman Mill due to a failed superheater loop on No.1 boiler.

- The harvesting sector has been advised to stop harvesting immediately.
- We are assessing the situation and mobilising crews for repairs.
- We are force-cooling the boiler to enable crews to access the affected area as soon as possible.
- At this stage, the repairs are expected to take about 30 to 36 hours.
- We will keep you updated.

Best regards

PAUL TURNBULL

Burdekin Regional Operations Manager

Copyright © 2021 Wilmar Sugar Australia, All rights reserved.
