



Sunday, 5 December 2021

Today's loading has been reduced due to re-start issues at Inkerman Mill.

- Contaminated condensate entered the boiler feedwater system last night, resulting in the boilers being taken offline to drain and refill.
- The site crushed through the night on one train, after boiler 1 was refilled with clean water.
- The two smaller boilers were kept offline due to other start-up issues.
- We expect to resume dual-side crushing operations early this afternoon when boiler 2 is brought back online.

Best regards

PAUL TURNBULL

Burdekin Regional Operations Manager

Copyright © 2021 Wilmar Sugar Australia, All rights reserved.

You are receiving this because you are a valued customer of Wilmar Sugar Australia.

Our mailing address is:

Wilmar Sugar Australia
Level 1, 5-21 Denham Street
Townsville, QLD 4810
Australia

[Add us to your address book](#)

