



**Tuesday, 29 October 2024**

Late yesterday afternoon we identified a vibration issue on No.5 mill.

- Our maintenance team worked through the night and identified a cracked high-speed shaft.
- We have developed a repair plan and commenced work this morning.
- We expect to resume crushing tomorrow (Wednesday).
- Our logistics team will be in contact to discuss loading requirements.

Best regards

**JAMES WALLACE**

Group Manager Operations (Sugar)



*Copyright © 2024 Wilmar Sugar Australia, All rights reserved.*

You are receiving this email because you are a valued stakeholder of Wilmar Sugar Australia.

**Our mailing address is:**

Wilmar Sugar Australia  
Level 1  
5-21 Denham Street  
Townsville, QLD 4810  
Australia

[Add us to your address book](#)

[unsubscribe from this list](#) [update subscription preferences](#)