HARVEST MANAGEMENT GROUP MEETING NOTES WEDNESDAY 21ST OCTOBER 2020

ESTIMATES

MILL	STD ALLOCATED	STD ORIGINAL HARVEST	STD LATEST HARV	STD ACT/ORIG	STD ACT/LATEST	ADJUSTED ESTIMATE	ESTIMATED REMAINS	STD HA HARV	STD AVE YIELD TPH
INVICTA	2,488,865	2,456,469	2,464,145	101.32%	101.00%	3,036,517	547,653	20,529	121.2
PIONEER	1,208,863	1,194,974	1,205,384	101.16%	100.29%	1,634,722	425,859	9,226	131.0
KALAMIA	1,254,887	1,267,372	1,305,074	99.01%	96.15%	1,622,670	367,783	9,578	131.0
INKERMAN	1,243,028	1,282,727	1,309,188	96.91%	94.95%	1,712,389	469,361	10,122	122.8
BURDEKIN	6,195,643	6,201,542	6,283,791	99.90%	98.69%	8,006,298	2,958,042	39,803	128.1

- Invicta Crush rate 25 tonnes per hour under budget and currently being limited by feeding station as a result of lower bin weights. Pan stage capacity still available despite sharp increase in CCS.
- Pioneer availability, tonnes crushed -93,582 are behind budget with crush rate only marginally less than budget by 1.0TPH. Throughput currently limited at pan stage. Evidence of CCS decline in the past 2 weeks.
- Kalamia availability on budget, tonnes crushed -46852 down on budget with crush rate marginally above budget by 2.0TPH. Issues clarifier feed launders choking, derailment of bins prior/post tip with investigations continuing.
- Inkerman availability well down, tonnes -113562 under budget with actual crush rate on forecast. Recent extended stop to repair boiler tube leaks uncovered multiple unknown leaks resulting in 60 hour stoppage. Major stoppage as a result Ergon power bump/alternator rotor failure. Power grid input and 4 mobile generators currently allowing milling operations to continue. Repaired rotor due back on site today with a stoppage of 24 hours to reinstall.

CANE TRANSFER & PROJECTED FINISH DATES

	INVICTA	PIONEER	KALAMIA	INKERMAN
EQUITY REPORT REMAINS	547,653	425,859	367,783	469,361
CANE TRANSFERS	44,290	-11,000	-17,850	-15,440
ACTUAL TO BE CRUSHED	591,943	414,859	349,933	453,921
PROJECTED FINISH DATES	#15-NOV	#24-NOV	#20-NOV	#24-NOV

[#] No allowance for wet weather events or unscheduled mill stoppages.

SAFETY INCIDENTS

- Itinerant worker vehicle clipped loco at "Swindley" this week
- All cane transfers from Inkermann across the river resulted in no incidents
- WHS inspector had a recent adverse interaction with haulout operator in the region

GENERAL BUSINESS

- 1. Haulout Vehicles it has been highlighted that at times vehicles travelling on main highway during darkness that visibility of taillights to following traffic can be difficult to see due to build-up of dirt/grime etc.
- 2. In Field Sidings incidents at sidings have continued in the Invicta area whereby bins had to be left behind due to becoming bogged due to build-up of billets etc. In terms of CSA Schedule 6, clause 9, it is the grower's responsibility to ensure their delivery point/s are cleaned from time to time and maintained in a clean and serviceable state.